



Fig. 1



3/9




Fig. 4




Fig. 5





Fig. 7





Fig. 9

5/9




Fig. 10







Fig. 12



Option 1
Weld on outside
of chamber



Option 2
Weld on either side
of chamber



Option 3
Electro - Fusion
Socket on outside

Fig. 11




Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24